US EPA RECORDS CENTER REGION 5

ECONOMY PLATING CO., INC. 1185 Bloor Lane Zionsville, In. 46077

(317) 873-2513

December 18, 1987

Janet Haff U.S. Environmental Protection Agency, 5HE-12 230 South Dearborn Street Chicago, Illinois 60604



To Whom It May Concern:

I am going to attempt to convey all I know about the Enviro-Chem/Northside Landfill problem in Zionsville, In., even though I've been unable to find any records pretaining to our involvement with these sites. My father handled the paper work for the company at that time and he passed away in May of 1984. I do remember that we were having metal hydroxide sludges from our waste treatment system hauled to Northside Landfill for disposal by Coghill Septic Service. Coghill's truck would hold two thousand gallons but we seldom filled it. We had it pumped every month or two.

There was only three of us working here at the time and our business was quite small. We were using no flocking material at that time so for the better part it was water that Coghill was hauling for us. At some point, I couldn't say when, the I S B H informed us that we could continue to send our waste to Northside but it would have to be mixed with dirt at the landfill and placed in an area separate from municipal waste. They supervised discharge of our waste at the landfill on occasion during the period of about one year, I believe it was about 1974 or 1975. They decided later that it was not wise discharging our sludge at Northside, so the I S B H informed us we would have to start transporting our waste to Caldwell Landfill. I believe Caldwell Landfill is located near Fortville. We continued to have it taken there until they closed. The state then said we should take our waste to Four County Landfill near Silverlake. I don't know how many trips Coghill make to Silverlake but I don't think many trips were made.

In the meantime Economy Plating Co., Inc. put in a centrifuge and started dewatering the sludge and put it in 30 gallon drums and later in 55 gallon drums. This is when we became involved with Enviro-Chem. Mike Finton, one of the original owners of Enviro-Chem was a former I S B H inspector who had inspected our company. Enviro-Chem had a license to haul hazardous waste and we didn't so Mike and I made a deal. His truck would come by our shop in Zionsville and pick up the drums of sludge and they would transport it, along with other waste, to Four County Landfill. We paid them for both the transportation and the disposal of the drums. They would then remanifest it and haul it to Four County. After Enviro-Chem went into receivership we continued having them haul for us until they closed. We were required by Enviro-Chem for the last few months they were in business to pay at the time of pick-up for transportation, disposal, and insurance costs. I don't recall what they were charging for there service's at that time but I do recall the insurance was \$1.00 a drum.

After Enviro-Chem closed we had a company out of Indianapolis; now called H E S, Inc.; haul our waste for us. H E S, Inc. hauled our waste to Four County a time or two. Later they began to take it to there plant for further treatment and disposal. Later we found it was more economical to have them pick it up in bulk form. We then discontinued the use of the centrifuge.

It wasn't until after Enviro-Chem closed and the EPA became involved that we learned that Enviro-Chem had set 83 drums of our sludge off at the Zionsville

location instead of taking it to the landfill.

I am sending you an analysis of the metal hydroxide waste that we are sending to H E S, Inc. I believe it is a good representative of what we have now and what we have always had. We've added nothing to our plating lines since the days Coghill Septic Service was hauling our waste. We have upgraded our treatment systems but our waste streams haven't changed.

I hope this letter explains our envolvement with these two companys, and if

there's any other information you need I will be happy to help if I can.

Respectfully Yours,

State of Indiana

Personally appeared before me.

Notary Edich More Coxley

This day 21st of Dec. 19 89

My Commission expires April 24 19 89

My/dsg

Respectfully Yours,

David H. Yates

President

Economy Plating Co., Inc.

DHY/dsg CC/file

₩ASTE	ANALYSIS PERM	IANENT RECORI	Ilu	dae		REVIEW !
ite Received:	Type of Re	port: Pa	ort B	Part C		
nerator's EPA ID Number IND 006414619	Lienerator"s A	of Generator	et. Box	NO., 5184	le, Zip)	
enerator's Name:		y Plactic	V	<u>+ 4 C.</u>		
317-873 - 2513 none Number:	Figure Co	//c Indicate:	.460	73	·	
DESCRIPTION OF WASTE Hazardous Weste Solid NOS. ORME		EPA HAZARDOUS WASTE MO	HAND- LING METHOD (code)	AMOUNT OF WASTE	UNIT MEASURE (code)	
					S S S S S S S S S S S S S S S S S S S	ļ
		F-006				<b></b>
	<del></del>					
omments: Process Generating	Haste	007	 			<u> </u>
- Metal Hydroxid HYSICAL STATE 025°C (Check Solid: Dusting hazard 1f	es from	Precious	Metal	chate ext	traction	attache
opened? Liquid/Sludges: 12,4 % Solidph Waste can be pumped?or poured? Liquid/Solid Phases: % Solid  of free flowing liquid layer  Water			Flammable: Flash Point Chemically reactive: Toxic Corrosive Irritae Odor Explosive Infect Volatility (if greater than account of the control			
IDENTIFY MAJOR COMPONENTS: If greater of waste content. Hinor components must add up Compound or Element:	Total major a	nd 1	. a. Par	PLETED BY ameter of (Gene ection Ra	Analysi erator-La	s: b-Proce
41NOR COMPONENTS: Concentrat or point of waste content (Ele INORGANIC METALS:		mg/1, 3		Hazaro Method Us ing Metho		<u>-</u>
Lead 5. Hercury  1. 9430 ns/e Zinc 6. Beryllium  1. 1434 ns/e Nickel 7. Cadmium			4. Frequency of Review: 5. Generator's Load Analysis (maequivalent:			
3.8 mg/c Silver Chromium  Hexavalent Chromium			1. Processing Procedure Used:			
INURGANIC NON-METALS:  Chlorine 13. Bromine 14.	Phosp Sulfu 80 8/4a Cyani	r ·· · · · · de	wthorize	pling Met d Signatu		cessor
/olume of Waste Material and the Waste Material contact ROMATIC AMINES; PESTICIDES; POLYCYC	in any of the UREAS OR THIO	following: UREAS; CYCL! ASBESTOS; AF	IC NITROG IY OTHER	EN (e.a.	PYRIDINE	T:PHEN

ECONOMY PLATING Co., Inc. 1185 Bloor Ln. Zionsville, IN 46077





Janet Haff U.S. Environmental Protection Agency, 5HE-12 230 South Dearborn Street Chicago, Illinois 60604

http://millinglinglight

Division of Land Pollution Control
JNDIANA STATE BOARD OF HEALTH
1330 West Michigan Street
P. O. Box 1964
Indianapolis, Indiana 46206

6

8





## $\Gamma$ ORM $\mathbf{F}$ : FACILITY ANNUAL REPORT FOR THE YEAR ENDING DEC. 31, 19 82

## **ENVIRONMENTAL MANAGEMENT BOARD** (Collected under the authority of IC 13-7-8.5-2 Indiana Environmental Management Act) XIV. FACILITY'S EPA ID NUMBER 및 N 파이이(6)이(5) 왕 5) 당·6 COST ESTIMATES FOR FACILITIES This information is required only on one copy of Form F. XV. COST ESTIMATE FOR FACILITY CLOSURE B. COST ESTIMATE FOR POST CLOSURE MONITORING AND MAINTENANCE 00 XVI. GENERATOR'S NAME (specify) GENERATOR'S EPA ID NUMBER ECONOMIYI IPILIAITILINGI ICIOI WD1010R 141141611 XVII. GENERATOR'S ADDRESS Street or P. O. Box RIR # 2 | 1810 | XI FILOIMS INTITUE IT State Zip 4601717 City or Town XVIII. WASTE IDENTIFICATION (B.) (C.) N (E.) (D.)**HAZARDOUS** U HAND-UNIT OF (A.)**AMOUNT** М WASTE LING WEIGHT 1 DESCRIPTION OF WASTE OF WASTE B NUMBER METHOD (circle N (in Pounds (see codes) (code)\* one) E or Tons) P030 501 WASTE CYANIDE, LIQUID T, P 2 T Ť 3 T T 5

XIX. COMMENTS (enter information by line number -- see instructions)

\* See Section XVIII-C of instructions for wastes handled by more than one method.

Ţ

T

T

P



## environmental conservation & chemical corporation

865 South U.S. 421 Zionsville, Indiana 46077 (317), 769-6153

March 5, 1982

Economy Plating 1185 Bloor Lane Zionsville, Indiana 46077

ATTN: David Yates

Dear Mr. Yates:

As a valued customer, ECC reclamation and disposal programs have your liability as a Generator as top priority for proper disposal of your hazardous waste material. Therefore, under Regulation 40 CFR, Part 262.11 and 40 CFR, Part 265.13 in the Federal Code of Regulations, the Generator is responsible for keeping on file the identity of each waste stream and sending that information to the Treatment, Storage & Disposal Facility.

To make the task easier, ECC has enclosed a Waste Product Record form so that you may conform to this regulation; Material Safety Data Sheets do not have the complete information needed. Please fill-out <u>all</u> information pertaining to your waste stream. All "letters" marked on the Waste Product Record must be answered. If you are unable to answer any of the necessary information, ECC can perform the particular lab tests required for a small fee. ECC will need this form completed before our next pick-up.

Please remember we enjoy doing business with your company and want to proceed according to the rules and regulations of the federal government.

If you have any questions please contact at our office.

Sincerely,

Christopher J. Werling,

Sales Manager

CJW:sar

Enclosure